

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	139	(242/326.4).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/02/20 12:00
L2	125	(242/324.3).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/02/20 12:00
L3	7082	guide same (groove slot cam) same arm same tape	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:06
L4	147631	("360"/\$.ccls. "242"/\$.ccls.)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:06
L5	164432	3 adn 4	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:02
L6	1828	3 and 4	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:02
L7	1000	("360"/85.ccls. "242"/338.ccls.)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:06
L8	25871	guide same (groove slot cam) same arm same (projection protuberance bump)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:19
L9	69	7 and 8	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:16
L10	105	(360/130.22).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/02/20 12:20
L11	286	(360/130.21).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/02/20 12:18
L12	60	11 and (projection protuberance bump)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:22
L13	120	(360/130.23).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/02/20 12:20
L14	0	306/85.ccls. and (projection protuberance bump)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:22
L15	313	360/85.ccls. and (projection protuberance bump)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:22

EAST Search History

L16	289	360/85.ccls. and ((projection protuberance bump) and guide)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:23
L17	204	360/85.ccls. and ((projection protuberance bump) same guide)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:23
L18	97	360/85.ccls. and ((projection protuberance bump) same guide same arm)	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:23
L19	13	("4562496" "4658310" "4692823" "4695906" "4975793" "5041928").PN. OR ("5369536").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:26
L20	48	(tape guide arm contact projection groove).clm.	US-PGPUB; USPAT; USOCR	AND	ON	2007/02/20 12:28
L21	1	(chassis fixed tape guide arm contact projection groove).clm.	US-PGPUB; USPAT; USOCR	AND	ON	2007/02/20 12:27
L22	0	(davis-david.xp. davis-david.xa.) and 360/85.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:29
L23	8	(davis-d\$.xp. davis-d\$.xa.) and 360/85.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:30
L24	18	("4410919" "4685008" "4796115" "4814910" "4918551" "4985789" "5025331" "5126909").PN. OR ("5291351").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:32
L25	1472	360/85	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:32
S1	773	(360/85).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/03/17 08:01
S2	695	(@ad<"20020417" @rlad<"20020417") and S1	US-PGPUB; USPAT; USOCR	OR	ON	2006/03/17 08:02
S3	118	(groove with chassis) and S2	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 11:59
S4	14	("4951164" "4975793" "5031056" "5070422" "5151832" "5278707").PN. OR ("5731925").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/03/17 08:18
S5	25	((fixed main) near2 chassis) with (slot groove) with (shaft post pole) and (guide with (receiving stop\$3))	US-PGPUB; USPAT; USOCR	OR	ON	2007/02/20 12:01
S6	0	("2005/0094310").URPN.	USPAT	OR	ON	2006/03/17 08:22

EAST Search History

S7	10	("4322761" "4520411").PN. OR ("4642713").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/03/17 08:26
S8	0	((fixed main) near2 chassis) with (slot groove) with (shaft post pole) and (guide with (receiving stop\$3))	JPO; DERWENT	OR	ON	2006/03/17 09:27
S9	0	"10510703"	US-PGPUB; USPAT; USOCR	OR	ON	2006/03/17 09:28
S10	1	"10/510703"	US-PGPUB; USPAT; USOCR	OR	ON	2006/03/17 09:28